



Planting Space for Trees:
Inadequate

Rows of Sidewalk Trees:
Discontinuous

Excessive Roadway Width:
Encourages Speeding

Bicycles:
Travel with Cars

Sidewalk Width:
Narrow (8 ft.)

Width of Pedestrian Refuge:
Inadequate (4 ft.)

Average Time to Cross Street:
30 Sec.

Median along Turn-Lane:
Too narrow for Trees